

# 身体汚染発生状況報告(平成29年12月)

場所: 免震重要棟2階非管理区域 汚染検査所

(単位: 件)

| 日  | 4Bq/cm <sup>2</sup> 以上の汚染 | 除染等の措置完了 |
|----|---------------------------|----------|
| 1  | 0                         | 0        |
| 2  | 0                         | 0        |
| 3  | 0                         | 0        |
| 4  | 0                         | 0        |
| 5  | 0                         | 0        |
| 6  | 1                         | 1        |
| 7  | 0                         | 0        |
| 8  | 0                         | 0        |
| 9  | 0                         | 0        |
| 10 | 0                         | 0        |
| 11 | 0                         | 0        |
| 12 | 0                         | 0        |
| 13 | 0                         | 0        |
| 14 | 0                         | 0        |
| 15 | 0                         | 0        |
| 16 | 0                         | 0        |
| 17 | 0                         | 0        |
| 18 | 0                         | 0        |
| 19 | 0                         | 0        |
| 20 | 0                         | 0        |
| 21 | 0                         | 0        |
| 22 | 0                         | 0        |
| 23 | 0                         | 0        |
| 24 | 0                         | 0        |
| 25 | 0                         | 0        |
| 26 | 0                         | 0        |
| 27 | 0                         | 0        |
| 28 | 0                         | 0        |
| 29 | 0                         | 0        |
| 30 | 0                         | 0        |
| 31 | 0                         | 0        |
| 合計 | 1                         | 1        |