

# 身体汚染発生状況報告(2020年4月)

場所: 雑固体廃棄物焼却設備建屋

(単位: 件数)

日	身体汚染 (表面汚染密度: 4Bq/cm <sup>2</sup> )	下着汚染 (表面汚染密度: 4Bq/cm <sup>2</sup> )	一般服 (表面汚染密度: 4Bq/cm <sup>2</sup> )	装備汚染 (表面汚染密度: 4Bq/cm <sup>2</sup> )
1	0	0	0	0
2	0	0	0	0
3	0	0	0	0
4	0	0	0	0
5	0	0	0	0
6	0	0	0	0
7	0	0	0	0
8	0	0	0	0
9	0	0	0	0
10	0	0	0	0
11	0	0	0	0
12	0	0	0	0
13	0	0	0	0
14	0	0	0	0
15	0	0	0	0
16	0	0	0	0
17	0	0	0	0
18	0	0	0	0
19	0	0	0	0
20	0	0	0	0
21	0	0	0	0
22	0	0	0	0
23	0	0	0	0
24	0	0	0	0
25	0	0	0	0
26	0	0	0	0
27	0	0	0	0
28	0	0	0	0
29	0	0	0	0
30	0	0	0	0
合計	0	0	0	0