

# 携行品汚染発生状況報告(2022年1月)

作成日	2022年2月1日(火)
作成者	
審査者	
承認者	

場所:事務本館 汚染検査所

(単位:件数)

日	4Bq/cm <sup>2</sup> 以上 40Bq/cm <sup>2</sup> 以下	40Bq/cm <sup>2</sup> 超過	汚染発生合計	除染措置	
				持出可	持出不可
1	0	0	0	0	0
2	0	0	0	0	0
3	0	0	0	0	0
4	0	0	0	0	0
5	1	0	1	0	1
6	2	0	2	0	2
7	0	0	0	0	0
8	0	0	0	0	0
9	0	0	0	0	0
10	0	0	0	0	0
11	1	0	1	0	1
12	3	0	3	0	3
13	4	0	4	0	4
14	1	0	1	0	1
15	0	0	0	0	0
16	0	0	0	0	0
17	1	0	1	0	1
18	3	0	3	0	3
19	2	0	2	0	2
20	4	0	4	0	4
21	1	0	1	0	1
22	1	0	1	0	1
23	0	0	0	0	0
24	3	0	3	0	3
25	1	0	1	0	1
26	2	0	2	0	2
27	0	0	0	0	0
28	1	0	1	0	1
29	0	0	0	0	0
30	0	0	0	0	0
31	0	0	0	0	0
合計	31	0	31	0	31

携行品汚染発生状況報告(2022年1月)

作成日	2022年2月1日(火)
作成者	
審査者	
承認者	

場所: 免震重要棟休憩所 第二工区

(単位: 件数)

日	4Bq/cm <sup>2</sup> 以上 40Bq/cm <sup>2</sup> 以下	40Bq/cm <sup>2</sup> 超過	汚染発生合計	除染措置	
				持出可	持出不可
1	0	0	0	0	0
2	0	0	0	0	0
3	0	0	0	0	0
4	0	0	0	0	0
5	0	0	0	0	0
6	0	0	0	0	0
7	0	0	0	0	0
8	0	0	0	0	0
9	0	0	0	0	0
10	0	0	0	0	0
11	1	0	1	0	1
12	1	0	1	0	1
13	0	0	0	0	0
14	0	0	0	0	0
15	0	0	0	0	0
16	0	0	0	0	0
17	0	0	0	0	0
18	0	0	0	0	0
19	0	0	0	0	0
20	2	0	2	0	2
21	0	0	0	0	0
22	0	0	0	0	0
23	0	0	0	0	0
24	0	0	0	0	0
25	0	0	0	0	0
26	0	0	0	0	0
27	0	0	0	0	0
28	0	0	0	0	0
29	0	0	0	0	0
30	0	0	0	0	0
31	0	0	0	0	0
合計	4	0	4	0	4

携行品汚染発生状況報告(2022年1月)

作成日	2022年2月1日(火)
作成者	
審査者	
承認者	

場所: 免震重要棟 2階 チェックポイント

(単位: 件数)

日	4Bq/cm <sup>2</sup> 以上 40Bq/cm <sup>2</sup> 以下	40Bq/cm <sup>2</sup> 超過	汚染発生合計	除染措置	
				持出可	持出不可
1	0	0	0	0	0
2	0	0	0	0	0
3	0	0	0	0	0
4	0	0	0	0	0
5	0	0	0	0	0
6	0	0	0	0	0
7	0	0	0	0	0
8	0	0	0	0	0
9	0	0	0	0	0
10	0	0	0	0	0
11	0	0	0	0	0
12	0	0	0	0	0
13	0	0	0	0	0
14	0	0	0	0	0
15	0	0	0	0	0
16	0	0	0	0	0
17	0	0	0	0	0
18	0	0	0	0	0
19	0	0	0	0	0
20	0	0	0	0	0
21	0	0	0	0	0
22	0	0	0	0	0
23	0	0	0	0	0
24	0	0	0	0	0
25	0	0	0	0	0
26	0	0	0	0	0
27	0	0	0	0	0
28	0	0	0	0	0
29	0	0	0	0	0
30	0	0	0	0	0
31	0	0	0	0	0
合計	0	0	0	0	0

携行品汚染発生状況報告(2022年1月)

作成日	2022年2月1日(火)
作成者	
審査者	
承認者	

場所:1/2号機 サービス建屋(1F) 休憩所

(単位:件数)

日	4Bq/cm <sup>2</sup> 以上 40Bq/cm <sup>2</sup> 以下	40Bq/cm <sup>2</sup> 超過	汚染発生合計	除染措置	
				持出可	持出不可
1	0	0	0	0	0
2	0	0	0	0	0
3	0	0	0	0	0
4	0	0	0	0	0
5	0	0	0	0	0
6	0	0	0	0	0
7	0	0	0	0	0
8	0	0	0	0	0
9	0	0	0	0	0
10	0	0	0	0	0
11	0	0	0	0	0
12	0	0	0	0	0
13	0	0	0	0	0
14	0	0	0	0	0
15	0	0	0	0	0
16	0	0	0	0	0
17	0	0	0	0	0
18	0	0	0	0	0
19	0	0	0	0	0
20	0	0	0	0	0
21	0	0	0	0	0
22	0	0	0	0	0
23	0	0	0	0	0
24	0	0	0	0	0
25	0	0	0	0	0
26	0	0	0	0	0
27	0	0	0	0	0
28	0	0	0	0	0
29	0	0	0	0	0
30	0	0	0	0	0
31	0	0	0	0	0
合計	0	0	0	0	0

携行品汚染発生状況報告(2022年1月)

作成日	2022年2月1日(火)
作成者	
審査者	
承認者	

場所:1/2号機 サービス建屋(1F) 装備交換所

(単位:件数)

日	4Bq/cm <sup>2</sup> 以上 40Bq/cm <sup>2</sup> 以下	40Bq/cm <sup>2</sup> 超過	汚染発生合計	除染措置	
				持出可	持出不可
1	0	0	0	0	0
2	0	0	0	0	0
3	0	0	0	0	0
4	0	0	0	0	0
5	0	0	0	0	0
6	0	0	0	0	0
7	0	0	0	0	0
8	0	0	0	0	0
9	0	0	0	0	0
10	0	0	0	0	0
11	0	0	0	0	0
12	0	0	0	0	0
13	0	0	0	0	0
14	0	0	0	0	0
15	0	0	0	0	0
16	0	0	0	0	0
17	0	0	0	0	0
18	0	0	0	0	0
19	0	0	0	0	0
20	0	0	0	0	0
21	0	0	0	0	0
22	0	0	0	0	0
23	0	0	0	0	0
24	0	0	0	0	0
25	0	0	0	0	0
26	0	0	0	0	0
27	0	0	0	0	0
28	0	0	0	0	0
29	0	0	0	0	0
30	0	0	0	0	0
31	0	0	0	0	0
合計	0	0	0	0	0

携行品汚染発生状況報告(2022年1月)

作成日	2022年2月1日(火)
作成者	
審査者	
承認者	

場所:1/2号機 サービス建屋(2F) 休憩所

(単位:件数)

日	4Bq/cm <sup>2</sup> 以上 40Bq/cm <sup>2</sup> 以下	40Bq/cm <sup>2</sup> 超過	汚染発生合計	除染措置	
				持出可	持出不可
1	0	0	0	0	0
2	0	0	0	0	0
3	0	0	0	0	0
4	0	0	0	0	0
5	0	0	0	0	0
6	0	0	0	0	0
7	0	0	0	0	0
8	0	0	0	0	0
9	0	0	0	0	0
10	0	0	0	0	0
11	0	0	0	0	0
12	0	0	0	0	0
13	0	0	0	0	0
14	0	0	0	0	0
15	0	0	0	0	0
16	0	0	0	0	0
17	0	0	0	0	0
18	0	0	0	0	0
19	0	0	0	0	0
20	0	0	0	0	0
21	0	0	0	0	0
22	0	0	0	0	0
23	0	0	0	0	0
24	0	0	0	0	0
25	0	0	0	0	0
26	0	0	0	0	0
27	0	0	0	0	0
28	0	0	0	0	0
29	0	0	0	0	0
30	0	0	0	0	0
31	0	0	0	0	0
合計	0	0	0	0	0

携行品汚染発生状況報告(2022年1月)

作成日	2022年2月1日(火)
作成者	
審査者	
承認者	

場所:3/4号機 サービス建屋(2F) 休憩所

(単位:件数)

日	4Bq/cm <sup>2</sup> 以上 40Bq/cm <sup>2</sup> 以下	40Bq/cm <sup>2</sup> 超過	汚染発生合計	除染措置	
				持出可	持出不可
1	0	0	0	0	0
2	0	0	0	0	0
3	0	0	0	0	0
4	0	0	0	0	0
5	0	0	0	0	0
6	0	0	0	0	0
7	0	0	0	0	0
8	0	0	0	0	0
9	0	0	0	0	0
10	0	0	0	0	0
11	0	0	0	0	0
12	0	0	0	0	0
13	0	0	0	0	0
14	0	0	0	0	0
15	0	0	0	0	0
16	0	0	0	0	0
17	0	0	0	0	0
18	0	0	0	0	0
19	0	0	0	0	0
20	0	0	0	0	0
21	0	0	0	0	0
22	0	0	0	0	0
23	0	0	0	0	0
24	0	0	0	0	0
25	0	0	0	0	0
26	0	0	0	0	0
27	0	0	0	0	0
28	0	0	0	0	0
29	0	0	0	0	0
30	0	0	0	0	0
31	0	0	0	0	0
合計	0	0	0	0	0

携行品汚染発生状況報告(2022年1月)

作成日	2月 1日 (火)
作成者	
審査者	
承認者	

場所： 5/6号機サービス建屋休憩所

(単位:件数)

日	4Bq/cm <sup>2</sup> 以上 40Bq/cm <sup>2</sup> 以下	40Bq/cm <sup>2</sup> 超過	汚染発生合計	除染措置	
				持出可	持出不可
1	0	0	0	0	0
2	0	0	0	0	0
3	0	0	0	0	0
4	0	0	0	0	0
5	0	0	0	0	0
6	0	0	0	0	0
7	0	0	0	0	0
8	0	0	0	0	0
9	0	0	0	0	0
10	0	0	0	0	0
11	0	0	0	0	0
12	0	0	0	0	0
13	0	0	0	0	0
14	0	0	0	0	0
15	0	0	0	0	0
16	0	0	0	0	0
17	0	0	0	0	0
18	0	0	0	0	0
19	0	0	0	0	0
20	0	0	0	0	0
21	0	0	0	0	0
22	0	0	0	0	0
23	0	0	0	0	0
24	0	0	0	0	0
25	0	0	0	0	0
26	0	0	0	0	0
27	0	0	0	0	0
28	0	0	0	0	0
29	0	0	0	0	0
30	0	0	0	0	0
31	0	0	0	0	0
合計	0	0	0	0	0



携行品汚染発生状況報告(2022年1月)

作成日	2月 1日 (火)
作成者	
審査者	
承認者	

場所： 企業センターA棟休憩所

(単位:件数)

日	4Bq/cm <sup>2</sup> 以上 40Bq/cm <sup>2</sup> 以下	40Bq/cm <sup>2</sup> 超過	汚染発生合計	除染措置	
				持出可	持出不可
1	0	0	0	0	0
2	0	0	0	0	0
3	0	0	0	0	0
4	0	0	0	0	0
5	0	0	0	0	0
6	0	0	0	0	0
7	0	0	0	0	0
8	0	0	0	0	0
9	0	0	0	0	0
10	0	0	0	0	0
11	0	0	0	0	0
12	0	0	0	0	0
13	0	0	0	0	0
14	0	0	0	0	0
15	0	0	0	0	0
16	0	0	0	0	0
17	0	0	0	0	0
18	0	0	0	0	0
19	0	0	0	0	0
20	0	0	0	0	0
21	0	0	0	0	0
22	0	0	0	0	0
23	0	0	0	0	0
24	0	0	0	0	0
25	0	0	0	0	0
26	0	0	0	0	0
27	0	0	0	0	0
28	0	0	0	0	0
29	0	0	0	0	0
30	0	0	0	0	0
31	0	0	0	0	0
合計	0	0	0	0	0

携行品汚染発生状況報告(2022年1月)

作成日	2月 1日 (火)
作成者	
審査者	
承認者	

場所： 企業センター厚生棟休憩所

(単位:件数)

日	4Bq/cm <sup>2</sup> 以上 40Bq/cm <sup>2</sup> 以下	40Bq/cm <sup>2</sup> 超過	汚染発生合計	除染措置	
				持出可	持出不可
1	0	0	0	0	0
2	0	0	0	0	0
3	0	0	0	0	0
4	0	0	0	0	0
5	0	0	0	0	0
6	0	0	0	0	0
7	0	0	0	0	0
8	0	0	0	0	0
9	0	0	0	0	0
10	0	0	0	0	0
11	0	0	0	0	0
12	0	0	0	0	0
13	0	0	0	0	0
14	0	0	0	0	0
15	0	0	0	0	0
16	0	0	0	0	0
17	0	0	0	0	0
18	0	0	0	0	0
19	0	0	0	0	0
20	0	0	0	0	0
21	0	0	0	0	0
22	0	0	0	0	0
23	0	0	0	0	0
24	0	0	0	0	0
25	0	0	0	0	0
26	0	0	0	0	0
27	0	0	0	0	0
28	0	0	0	0	0
29	0	0	0	0	0
30	0	0	0	0	0
31	0	0	0	0	0
合計	0	0	0	0	0

# 携行品汚染発生状況報告(2022年1月)

作成日	2月1日(火)
作成者	
審査者	
承認者	

場所:登録センター休憩所

(単位:件)

日	4Bq/cm <sup>2</sup> 以上 40Bq/cm <sup>2</sup> 以下	40Bq/cm <sup>2</sup> 超過	汚染発生合計	除染措置	
				持出可	持出不可
1	0	0	0	0	0
2	0	0	0	0	0
3	0	0	0	0	0
4	0	0	0	0	0
5	0	0	0	0	0
6	0	0	0	0	0
7	0	0	0	0	0
8	0	0	0	0	0
9	0	0	0	0	0
10	0	0	0	0	0
11	0	0	0	0	0
12	0	0	0	0	0
13	0	0	0	0	0
14	0	0	0	0	0
15	0	0	0	0	0
16	0	0	0	0	0
17	0	0	0	0	0
18	0	0	0	0	0
19	0	0	0	0	0
20	0	0	0	0	0
21	0	0	0	0	0
22	0	0	0	0	0
23	0	0	0	0	0
24	0	0	0	0	0
25	0	0	0	0	0
26	0	0	0	0	0
27	0	0	0	0	0
28	0	0	0	0	0
29	0	0	0	0	0
30	0	0	0	0	0
31	0	0	0	0	0
合計	0	0	0	0	0

# 携行品汚染発生状況報告(2022年1月)

場所:土捨て場休憩所

(単位:件)

作成日	2月1日(火)
作成者	
審査者	
承認者	

日	4Bq/cm <sup>2</sup> 以上 40Bq/cm <sup>2</sup> 以下	40Bq/cm <sup>2</sup> 超過	汚染発生合計	除染措置	
				持出可	持出不可
1	0	0	0	0	0
2	0	0	0	0	0
3	0	0	0	0	0
4	0	0	0	0	0
5	0	0	0	0	0
6	0	0	0	0	0
7	0	0	0	0	0
8	0	0	0	0	0
9	0	0	0	0	0
10	0	0	0	0	0
11	0	0	0	0	0
12	0	0	0	0	0
13	0	0	0	0	0
14	0	0	0	0	0
15	0	0	0	0	0
16	0	0	0	0	0
17	0	0	0	0	0
18	0	0	0	0	0
19	0	0	0	0	0
20	0	0	0	0	0
21	0	0	0	0	0
22	0	0	0	0	0
23	0	0	0	0	0
24	0	0	0	0	0
25	0	0	0	0	0
26	0	0	0	0	0
27	0	0	0	0	0
28	0	0	0	0	0
29	0	0	0	0	0
30	0	0	0	0	0
31	0	0	0	0	0
合計	0	0	0	0	0

携行品汚染発生状況報告(2022年1月)

作成日	2月1日(火)
作成者	
審査者	
承認者	

場所:入退域管理施設

(単位:件)

日	4Bq/cm <sup>2</sup> 以上 40Bq/cm <sup>2</sup> 以下	40Bq/cm <sup>2</sup> 超過	汚染発生合計	除染措置	
				搬出可	搬出不可
1	0	0	0	0	0
2	0	0	0	0	0
3	0	0	0	0	0
4	0	0	0	0	0
5	1	0	1	1	0
6	0	0	0	0	0
7	0	0	0	0	0
8	0	0	0	0	0
9	0	0	0	0	0
10	0	0	0	0	0
11	3	0	3	0	3
12	0	0	0	0	0
13	4	0	4	0	4
14	2	0	2	0	2
15	0	0	0	0	0
16	0	0	0	0	0
17	0	0	0	0	0
18	0	0	0	0	0
19	0	0	0	0	0
20	0	0	0	0	0
21	0	0	0	0	0
22	1	0	1	0	1
23	0	0	0	0	0
24	3	0	3	0	3
25	1	0	1	0	1
26	0	0	0	0	0
27	1	0	1	0	1
28	0	0	0	0	0
29	1	0	1	0	1
30	0	0	0	0	0
31	1	0	1	0	1
合計	18	0	18	1	17

携行品汚染発生状況報告(2022年1月)

作成日	2月1日(火)
作成者	
審査者	
承認者	

場所: 雑固体廃棄物焼却設備建屋(管理区域)

(単位: 件)

日	4Bq/cm <sup>2</sup> 以上 40Bq/cm <sup>2</sup> 以下	40Bq/cm <sup>2</sup> 超過	汚染発生合計	除染措置	
				搬出可	搬出不可
1	0	0	0	0	0
2	0	0	0	0	0
3	0	0	0	0	0
4	0	0	0	0	0
5	0	0	0	0	0
6	0	0	0	0	0
7	0	0	0	0	0
8	0	0	0	0	0
9	0	0	0	0	0
10	0	0	0	0	0
11	0	0	0	0	0
12	0	0	0	0	0
13	0	0	0	0	0
14	0	0	0	0	0
15	0	0	0	0	0
16	0	0	0	0	0
17	0	0	0	0	0
18	0	0	0	0	0
19	0	0	0	0	0
20	0	0	0	0	0
21	0	0	0	0	0
22	0	0	0	0	0
23	0	0	0	0	0
24	0	0	0	0	0
25	0	0	0	0	0
26	0	0	0	0	0
27	0	0	0	0	0
28	0	0	0	0	0
29	0	0	0	0	0
30	0	0	0	0	0
31	0	0	0	0	0
合計	0	0	0	0	0

携行品汚染発生状況報告(2022年1月)

作成日	2月1日(火)
作成者	
審査者	
承認者	

場所: 雑固体廃棄物焼却設備建屋(管理対象区域)

(単位: 件)

日	4Bq/cm <sup>2</sup> 以上 40Bq/cm <sup>2</sup> 以下	40Bq/cm <sup>2</sup> 超過	汚染発生合計	除染措置	
				搬出可	搬出不可
1	0	0	0	0	0
2	0	0	0	0	0
3	0	0	0	0	0
4	0	0	0	0	0
5	0	0	0	0	0
6	0	0	0	0	0
7	0	0	0	0	0
8	0	0	0	0	0
9	0	0	0	0	0
10	0	0	0	0	0
11	0	0	0	0	0
12	0	0	0	0	0
13	0	0	0	0	0
14	0	0	0	0	0
15	0	0	0	0	0
16	0	0	0	0	0
17	0	0	0	0	0
18	0	0	0	0	0
19	0	0	0	0	0
20	0	0	0	0	0
21	0	0	0	0	0
22	0	0	0	0	0
23	0	0	0	0	0
24	0	0	0	0	0
25	0	0	0	0	0
26	0	0	0	0	0
27	0	0	0	0	0
28	0	0	0	0	0
29	0	0	0	0	0
30	0	0	0	0	0
31	0	0	0	0	0
合計	0	0	0	0	0

携行品汚染発生状況報告(2022年1月)

作成日	2月1日(火)
作成者	
審査者	
承認者	

場所:増設雑固体廃棄物焼却設備建屋(管理対象区域)

(単位:件)

日	4Bq/cm <sup>2</sup> 以上 40Bq/cm <sup>2</sup> 以下	40Bq/cm <sup>2</sup> 超過	汚染発生合計	除染措置	
				搬出可	搬出不可
1	0	0	0	0	0
2	0	0	0	0	0
3	0	0	0	0	0
4	0	0	0	0	0
5	0	0	0	0	0
6	0	0	0	0	0
7	0	0	0	0	0
8	0	0	0	0	0
9	0	0	0	0	0
10	0	0	0	0	0
11	0	0	0	0	0
12	0	0	0	0	0
13	0	0	0	0	0
14	0	0	0	0	0
15	0	0	0	0	0
16	0	0	0	0	0
17	0	0	0	0	0
18	0	0	0	0	0
19	0	0	0	0	0
20	0	0	0	0	0
21	0	0	0	0	0
22	0	0	0	0	0
23	0	0	0	0	0
24	0	0	0	0	0
25	0	0	0	0	0
26	0	0	0	0	0
27	0	0	0	0	0
28	0	0	0	0	0
29	0	0	0	0	0
30	0	0	0	0	0
31	0	0	0	0	0
合計	0	0	0	0	0