Sampling Results Regarding the Influence on the Water Leak at a Tank in the H6 Area in Fukushima Daiichi Nuclear Power Station (Around the H6 Area) Tokyo Electric Power Company

			Unit: Bq/L
	Groundwater around H6 area		
	G-1	G-2	G-3
Date of Sampling		Mar 19, 2014	
Time of sampling		9:51 AM	
Gross β		120	
H-3 (Approx. 12 years)		Under analysis	

* "ND" indicates that the measurement result is below the detection limit, and the detection limit of each nuclide is provided in parentheses.



Photo offered by JAPAN SPACE IMAGING CORPORATION