

Analysis Results of Rainwater Obtained Inside the Dike at the Tank Area After Treated by the Rainwater Treatment System

<Mobile RO membrane system>

	Measurement result [Bq/L]		Sampling place	Sampling date	Sampling time
	Chemical Analysis Building *	Laboratory at Unit 5 and 6			
Cs-134	ND (6.8E-01)	ND (7.5E-01)	Treated water tank	Aug 7, 2014	5:30 PM
Cs-137	ND (5.3E-01)	1.3E+00			
Gross β	ND (4.1E+00)	ND (5.0E+00)			
Tritium	1.0E+03	8.9E+02	Receiving tank	Aug 5, 2014	1:25 PM
Notification density rate*	0.17	0.21			

* "ND" indicates that the measurement result is below the detection limit, and the detection limit of each nuclide is provided in parentheses.

* Analysis of tritium is performed at Environment Management Building.