



January 29, 2016
Tokyo Electric Power Company


Air Dose Rates inside the Buildings



Sampling Period

Unit 1: from November 1, 2015 to November 30, 2015











Fukushima Daiichi NPS

Unit 1 Reactor Building 5th Floor


[mSv/h]






Fukushima Daiichi NPS



Unit 1 Turbine Building 1st Basement Floor

[mSv/h]










Fukushima Daiichi NPS

Unit 2 Radioactive Waste Treatment Facility 1st Floor
Units 1 and 2 Drum Loading Dock



[mSv/h]



Fukushima Daiichi NPS

Units 1 and 2 Service Building 1st Floor

[mSv/h]



Fukushima Daiichi NPS

Units 1 and 2 Service Building 2nd Floor

[mSv/h]

