

February 29, 2015 Tokyo Electric Power Company

## Air Dose Rates inside the Buildings


**Sampling Period** 

Unit 1: from December 1, 2015 to December 31, 2015







Fukushima Daiichi NPS	Unit 1 Reactor Building 3rd Floor	[mSv/h]
-----------------------	-----------------------------------	---------




Fukushima Daiichi NPS	Unit 1 Reactor Building 4th Floor	[mSv/h]
-----------------------	-----------------------------------	---------





Fukushima Daiichi NPS Unit 1 Reactor Building 5th Floor [mSv/h]
---




An and a second se		
Fukushima Daiichi NPS	Unit 1 Turbine Building 1st Basement Floor	[mSv/h]








Fukushima Daiichi NPS Unit 1	Radioactive Waste Treatment Facility 1st Floor	[mSv/h]
------------------------------	--	---------



Fukushima Daiichi NPS	Unit 2 Radioactive Waste Treatment Facility 1st Floor Units 1 and 2 Drum Loading Dock	[	[mSv/h]
			4

Fukushima Daiichi NPS	Units 1 and 2 Service Building 1st Floor	[mSv/h]
-----------------------	--	---------



And a second second second second second second		
Fukushima Daiichi NPS	Units 1 and 2 Service Building 2nd Floor	[mSv/h]

