
January 29, 2016 Tokyo Electric Power Company

Air Dose Rates inside the Buildings

Sampling Period

Unit 2: from November 1, 2015 to November 30, 2015


Fukushima Daiichi NPS	Unit 2 Reactor Building Semi-Basement Floor	[mSv/h]
-----------------------	---	---------





Fukushima Daiichi NPS Unit 2 Reactor Building 1st Floor [mSv/h]
Image: Second conditions Image: Second c

Fukushima Daiichi NPS	Unit 2 Reactor Building 2nd Floor	[mSv/h]
	Eammability Heat Exchanger Heat Exchanger Contrel System	nger Inger
		anger

B








Fukushima Daiichi NPS

4


Unit 2 Turbine Building 1st Basement Floor

[mSv/h]

000 00 - Horney Contraction of the second se Ο -6 O 0 -œ⊞ D 0 5 0.0 п ₽ L 님 8 (B) (C) (A) P P 민 (B) (A) (B) (A) F High Pressure Condensate Pump 0 a (A) (B) (C) Ø **□ 3B** (B) (C) Θ 9 | | | (A) 🗆 (B) P 8 G Motor-Driven Ъ Reactor Feed Water Pump



Fukushima Daiichi NPS	Unit 2 Turbine Building 2nd Floor	[mSv/h]
-----------------------	-----------------------------------	---------



Fukushima Daiichi NPS	Unit 2 Radioactive Waste Treatment Facility 1st Floor	[mSv/h]
-----------------------	---	---------

