
May 31, 2015 Tokyo Electric Power Company Holdings, Inc.


Air Dose Rates inside the Buildings

Sampling Period


Unit 3: from March 1, 2016 to March 31, 2016



































Fukushima Daiichi NPS	Unit 3 Turbine Building 1st Floor	[mSv/h]
-----------------------	-----------------------------------	---------








[mSv/h]













Fukushima Daiichi NPS	Units 3 and 4 Service Building 1st Basement Floor	[mSv/h]
-----------------------	---------------------------------------------------	---------




Fukushima Daiichi NPS	Units 3 and 4 Service Building Semi-Basement Floor	[mSv/h]
-----------------------	----------------------------------------------------	---------



Fukushima Daiichi NPS Units 3 and 4 Service Building 1st Floor	[mSv/h]
----------------------------------------------------------------	---------





	THE STATE OF THE S	
Fukushima Daiichi NPS	Units 3 and 4 Service Building 2nd Floor	[mSv/h]

