

January 29, 2016 Tokyo Electric Power Company

Air Dose Rates inside the Buildings


Sampling Period

Unit 5: from November 1, 2015 to November 30, 2015













[mSv/h]



4





I _		
Fukushima	Daiichi	NPS
i airaoi iii ia	Danoin	

Unit 5 Reactor Building 4th Floor


[mSv/h]

1F05RB004-00-01
























Fukushima	Daiichi	NPS
ji ukusiiiila	Dalicili	111 0

Unit 5 Radioactive Waste Treatment Facility 1st Floor

[mSv/h]



Fukushima Daiichi NPS

Unit 5 Radioactive Waste Treatment Facility 2nd Floor

[mSv/h]

