
May 31, 2015 Tokyo Electric Power Company Holdings, Inc.


## Air Dose Rates inside the Buildings

Sampling Period

Unit 5: from March 1, 2016 to March 31, 2016












)











	Fukushima [	Daiichi	NPS
-	i ukusiiiila L	Janon	111 0

Unit 5 Reactor Building 4th Floor


[mSv/h]

1F05RB004-00-01
























Fukushima	Daiichi	NIDO
rukusiiiiia	Dalicili	INPO

Unit 5 Radioactive Waste Treatment Facility 1st Floor


[mSv/h]



i Fukusi iii ila Dalicii	Fukushima Daiichi	<b>NPS</b>
--------------------------	-------------------	------------


Unit 5 Radioactive Waste Treatment Facility 2nd Floor


[mSv/h]





Fukushima Daiichi NPS	Unit 5 Radioactive Waste Treatment Facility 3rd Floor	[mSv/h]
-----------------------	---	---------





Fukushima Daiichi NPS Units 5 and 6 Service Building 2nd Floor [mSv/h]
--

