


Condition of the Bank Protection Area at Fukushima Daiichi Nuclear Power Station


<Reference>
September 25, 2013
Tokyo Electric Power Company

■ Transition of the groundwater level between Unit 1 and 2 (August 24 - September 24)




* Automatic measurement data measured by water gauge

**■Progress Status of Ground Improvement Construction between Unit 1 and 2
(As of the Morning on September 25)**




* The range of the construction is subject to change depends on the site status.

■ Transition of the groundwater level between Unit 2 and 3 (August 24 - September 24)




* Automatic measurement data measured by water gauge

■ Progress Status of Ground Improvement Construction between Unit 2 and 3 (As of the Morning on September 25)



* The range of the construction is subject to change depends on the site status.


■ Transition of the groundwater level between Unit 3 and 4 (August 24 - September 24)



* Automatic measurement data measured by water gauge

■ Progress Status of Ground Improvement Construction between Unit 3 and 4 (As of the Morning on September 25)

Ground improvement (sea side): 29
out of 132 locations (construction
started on August 23, 2013)



* The range of the construction is subject to change depends on the site status.