


Smoke Coming out of the Control Panel of the Compressed Air System (IA System) at Unit 6 Turbine Building Basement at Fukushima Daiichi Nuclear Power Station (Follow-up)



Terminal of the primary winding (Photo taken from above the transformer)



The inside of winding got heated up and insulating varnish is melted



Terminal of the secondary winding (Photo taken from below the transformer)



Auxiliary transformer for IA dryer control circuit