

Investigation of the Inside of Unit 3 Spent Fuel Pool using an Underwater Camera at Fukushima Daiichi NPP (October 11·12)

Underwater camera investigation on October 11

- 19 workers involved
- From around 8:00 am to around 3:40 pm


Underwater camera investigation on October 12

- 18 workers involved
- From around 7:45 am to around 3:55 pm

<Reference>

October 15, 2012

Tokyo Electric Power Company



Pict① : Electric Motor of Fuel Exchanger



Pict② : Deck Plate



Pict③ : Fuel Storage Rack

[Legend]

- : Fuel storage rack
- : Areas investigated on Oct. 11
- : Area investigated on Oct. 12
- : Camera direction

※Photos ①② and ③④⑤ are captured images of the underwater camera video recorded on Oct. 11 and Oct. 12 respectively.



Pict⑤ : Endtrack of Fuel Exchanger



Pict④ : Deposited Material over Fuel Storage Rack