## Work Schedule of the Main Inspection/Restoration of the Kashiwazaki-Kariwa Nuclear Power Station in Response to the Niigata-Chuetsu-Oki Earthquake(during 4 Weeks)(1/1)

## [Inspection/Restoration Status] From March 13, 2011 (Sun) to April 9, 2011 (Sat)

	System / Equipment	Items	March 13 (Sun) to March 19 (Sat)	March 20 (Sun) to March 26 (Sat)	March 27 (Sun) to April 2 (Sat)	April 3 (Sun) to April 9 (Sat)	Status of
Unit 2	Turbine facilities	Turbine inspection					High-pressure turbine and low-pressure turbine (A) (B) (C) detailed
	Other facilities	Main transformer inspection					Carrying in and installation work commenced on Jun. 15, 2010.
		House transformer inspection					Carrying in and installation work commenced on Nov. 30, 2009.
		Excitation transformer inspection					Carrying in and installation work commenced on Nov. 30, 2009.
		Main generator inspection					Inspection commenced on Mar. 19, 2008.
		Main exhaust duct inspection / restoration					Preparation for restoration work commenced on Aug. 9, 2008. Reste commenced on Jul. 17, 2010.
	Seismic reinforcement	Seismic reinforcement works such as pipe supports					Reinforcement work commenced on Feb. 1, 2011.
		Seismic reinforcement works for reactor building overhead crane					Reinforcement work commenced on Jul. 31, 2010.
		Seismic reinforcement works for the fuel handling machine					Reinforcement work commenced on Jul. 27, 2010.
Unit 3	Reactor facilities	Primary containment vessel closure					Closure work commenced on Mar. 3, 2011.
	Verification of system integrity	System functional test					System functional test commenced on Nov. 16, 2010. Performance test for steam turbine (#2) conducted on Mar. 11, 2011 Partial interlock functional test of reactor protection system conducts
Unit 4	Turbine facilities	Turbine inspection					High-pressure turbine and low-pressure turbine (A) (B) (C) detailed High-pressure turbine and low-pressure turbine (A) (B) (C) restoration
	Other facilities	Main transformer inspection					Carrying in and installation work commenced on Aug. 28, 2009.
		House transformer inspection					Carrying in and installation work commenced on Sep. 2, 2009.
		Excitation transformer inspection					Carrying in and installation work commenced on Sep. 2, 2009.
		Main generator inspection					Inspection commenced on Jan. 15, 2008.
		Inspection of power supply input transformer of the primary loop recirculation system adjustable speed drive					Carrying in and installation work commenced on Jun. 12, 2009.
	Seismic reinforcement	Seismic reinforcement works such as pipe supports					Reinforcement work commenced on Jan. 17, 2011.
		Seismic reinforcement works for the fuel handling machine					Reinforcement work completed on Mar. 4, 2011.
hers	·	Restoration and reinforcement work for the on-site/ outside roads & slope, etc.					Restoration work for roads inside and outside of the site currently in Restoration work of Takamachi Overpass to be conducted from Apr.

\* Inspection results for each facilities will be announced as soon as they compiled.

\* Inspection and restoration work and execution date for each item may alter according to the situation.

\* Unit 1, Unit 5, Unit 6 and Unit 7 are in operation.

\* A part of restoration works to be postponed due to the influence of the Tohoku-Chihou-Taiheiyo-Oki Earthquake which occurred on March 11, 2011. The works will be resumed once ready.

of Inspection / Restoration
d inspection commenced on Dec. 7, 2009.
storation of substruction commenced on Dec. 1, 2008Restoration work of a duct
11. cted on Mar. 11, 2011.
ed inspection commenced on Aug. 3, 2009.
tion work commenced on Jul. 5, 2010.
in progress.
pr. 1, 2010 to Mar. 25, 2011.