

The results of nuclide analyses of plutonium in seawater taken
in areas near intake canal of Fukushima Daiichi Nuclear Power Station

1. Place of Sampling : north-side of intake canals of Unit 1-4 of Fukushima Daiichi Nuclear Power Station
2. Analysis Agency : Japan Chemical Analysis Center
3. Results of measurement :

(measure : mBq/L)

| Place of Sampling | Date of Sampling | Pu-238 | Pu-239,Pu-240 |
|---|------------------|--------------------------------|--------------------------------|
| North-side of intake canals of Unit 1-4 | 6/13 | N.D. [$<4.6 \times 10^{-1}$] | N.D. [$<4.5 \times 10^{-1}$] |

[]:detection limit

4. Evaluation:

According to this survey, Pu-238,Pu-239 and Pu-240 were not detected.

END